



SERVICE PARTS LIST

BULLETIN NO.
PN0008071

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
BOLT™ REDLITHIUM™ USB Cooling Fan			Oct. 2025
CATALOG NO.	48-73-1385	SERIAL NO.	R95A
		WIRING INSTRUCTION	

EXAMPLE:
00 0 Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).





FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	-----	Cap	(1)
2	-----	Cushion Pad	(1)
3	31-15-1385	O-ring	(1)
12	45-56-1385	Hook and Loop Strap	(1)
19	-----	Universal Duct	(1)
20	-----	Hard Hat Duct	(1)
21	-----	Helmet Duct	(1)
24	42-44-1210	USB-C to USB-A Cable	(1)
27	12-20-1386	Service Nameplate	(1)
30	31-12-1385	Battery Cap Kit	(1)
31	43-24-1385	Air Duct Kit	(1)

FIG. 27 NOTES
A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or name plate.

STRAP WEAVING INSTRUCTIONS


Step 1:

Weave strap (with hook and loop side up) down through Slot "A".




Step 2:

Pull strap up through Slot "B", so the end is tight to "C".



Step 4:

Pull strap across bracket, and weave through Slot "D".



Step 5:

Flip bracket over, and attach hook and loop.

