



## TO INFORM YOU

PRODUCT  
SUPPORT  
BULLETIN # 162

**TO:** Authorized Service Stations  
Branch Office/Service Centers  
Branch/Service Center Managers  
Regional Managers  
District Sales Managers

**DATE** March, 1987

**FROM:** Corbert A. Garb - National Service Manager

**TOOL(S)/PRODUCT(S) AFFECTED:** *DYMODRILLS* - Diamond Core Drills  
3820 3880 3940 4020 4025  
4029 4030 4034 4035 4039

**SUBJECT:** 14-46-4030 Service Kit

List Price \$20.70

14-46-4030 Service Kit is a Service Replacement Part available for servicing *DYMODRILLS* - DIAMOND CORE DRILLS - 3820, 3880, 3940, 4020, 4025, 4029, 4030, 4034, 4035 and 4039, allowing for replacement of the **most common** needed service items, at an *economical* price.

*This KIT contains...*

2ea	22-18-0055	CARBON BRUSH ASSEMBLY
1ea	34-40-1100	O-RING
1ea	34-40-1200	O-RING
2ea	34-40-1350	O-RING
1ea	34-60-1800	RETAINING RING
1ea	34-60-2115	RETAINING RING
1ea	44-60-0050	SHEAR PIN
2ea	45-06-0050	TROSTEL SEAL

This bulletin is for informational purposes; please note in Service Parts List Manual under 54-16-DIAMOND DRILLS.

MILWAUKEE ELECTRIC TOOL CORPORATION  
13135 W. LISBON RD., BROOKFIELD, WIS. 53005  
(414) 781-3600