



TO INFORM YOU

PRODUCT
SUPPORT
BULLETIN # 322

TO: AUTHORIZED *Portable Electric Tool* SERVICE STATIONS
BRANCH OFFICE/SERVICE CENTERS, BRANCH MANAGERS
REGIONAL MANAGERS, DISTRICT MANAGERS, SALES SUPPORT REPRESENTATIVES

DATE: JULY, 1998

FROM: Corbert A. Garb - National Service Manager

TOOL(S) \ PRODUCT(S) AFFECTED

6065-6, 6066-6, 6095, 6096 - 7"/ 9" 15AMP SANDER
6067-6, 6068-6, 6069, 6070, 6098 - 7"/ 9" 15AMP GRINDER

SUBJECT: DRY CUTTING MASONRY CORE BITS

MILWAUKEE ELECTRIC TOOL CORPORATION HAS BECOME AWARE OF *DRY DIAMOND* CORE BIT MANUFACTURES MAKING CLAIMS REGARDING 'DRY' CUTTING MASONRY DIAMOND CORE BITS THAT ARE DESIGNED TO MOUNT ON A 5/8"-11 THREADED SHAFT. THE MANUFACTURE(S) CLAIM THESE DRY CUT DIAMOND CORE BITS CAN BE SUCCESSFULLY USED ON RIGHT ANGLE SANDERS OR GRINDERS.

Milwaukee Electric Tool Corporation has received reports of Milwaukee Sander/Grinders being subjected to high electrical & mechanical loading (overloading) in this application. This overloading of the tool causes premature failure of components.

*Milwaukee Electric Tool Corporation **does not** recognize the use of dry cutting diamond core bits on right angle sanders or grinders as an appropriate application for these tools. Milwaukee Sander/Grinders used in this manner **should not be repaired under normal warranty repair circumstance**, as use of Sander/Grinders in this manner constitutes **misuse**.*

This bulletin is for informational purposes; PLEASE NOTE ON SERVICE PARTS LIST BULLETIN: DOMESTIC 54-38-0333, -0343, -0353, -0373, -0383, -0701, -0751, -0801