



SERVICE PARTS LIST



BULLETIN NO.
54-04-0260

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
POWER PLUS CHARGER			May '97
CATALOG NO. 48-59-0230	SERIAL NUMBER	WIRING INSTRUCTION	
48-59-0231	935A		

EXAMPLE:
Component Parts (Small #) Are Included
When Ordering The Assembly (Large #).

00 | 0

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	06-82-9207	6-32 x 11/16" Pan Hd. Slit. PT T-10	(4)
2	22-64-1070	Cordset	(1)
3	31-50-1550	Upper Housing	(1)
4		Lower Housing	(1)
5		Circuit Board Assembly	(1)
	12-20-0830	Service Nameplate Kit (48-59-0230)	(1)
	12-20-0310	Service Nameplate Kit (48-59-0231)	(1)



- FIG. NOTES**
- 4,5 Circuit board assembly to be fully seated on the lower housing screw bosses so that the top of the boss is flush with the top of the circuit board assembly.
- 1,3,4 Verify that the top housing is fully seated on the lower housing prior to installing the screws.

Capacitor to be placed between lower housing ribs with glue spots located underneath the middle of the capacitor.

1 (Nameplate) In recessed pocket on the bottom of lower housing.

