
## WIRING INSTRUCTIONS



	WIRING SPECIFICATIONS								
Wire No.	Wire Color	Origin or Part No.	Gauge	Length	Terminals, Connectors and End Wire Preparation				
1	White	23-94-6216			Strip .18" for T1, connect to right brush. Strip .5" and tin, connect to #9 with C1.	N			
2	Red	23-94-6221			Strip .18" for T1, connect to left brush. Strip .5" and tin, connect to #10 with C1.	Ι,			
3	Green	22-64-1231			Component of cord set. Strip .18" for T2. Ground to motor hsg. with screw.				
4	Black	18-50-0063			Component of field. Strip .18" for T2. Connect to '2A' on switch.	$\prod$			
5	White	22-64-1231			Component of cord set. Strip .18" for T2. Connect to '2B' on switch.	ΙĽ			
6	Black	22-64-1231			Component of cord set. Strip .18" for T2. Connect to '1B' on switch.	Ш			
7	Yellow	18-50-0063			Component of field. Strip .5" and tin, connect to #11 with C1.	$\parallel$			
8	Black	23-66-2517			Component of fwd./rev. switch. Strip .18" for T1. Connect to '1A' on switch.	11			
9	White	23-66-2517			Component of fwd./rev. switch. Strip .5" and tin, connect to #1 with C1.	10			
10	Red	23-66-2517			Component of fwd./rev. switch. Strip .5" and tin, connect to #2 with C1.	lΓ			
11	Yellow	23-66-2517			Component of fwd./rev. switch. Strip .5" and tin, connect to #7 with C1.	J٤			

## NOTE:

All leads must be held to  $\pm$  1/8". All lead lengths are before stripping.

TERMINAL DESCRIPTION								
Code	Part No.	Qnty.						
T1	23-74-0750	2						
T2	23-74-0850	5						
CONNECTOR DESCRIPTION								
C1	22-56-0150	3						
		Davie 1						