Milwaukee

SERVICE PARTS LIST

BULLETIN NO. 54-05-5325

SPECIFY CATALO	REVISED BULLETIN			
		Nov. 2019		
Dry Coring Attachment			WIRING INSTRUCTION	
CATALOG NO.	5319-DE	STARTING SERIAL NO	Wilding	10011011

00 0 EXAMPLE: Component Parts (Small #) Are Included When Ordering The Assembly (Large #).




FIG. 1 2 3 4 5	PART NO. 	DESCRIPTION OF PART Rubber Gasket Attachment Body Brush Ring Hose Clip Adaptor Nameplate (Not Shown)	NO. REQ. (1) (1) (1) (1) (1) (1)	FIG. 5	NOTES A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.
-------------------------------	--------------	--	----------------------------------	------------------	--