



SERVICE PARTS LIST

BULLETIN NO.
54-49-0283

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
52" HIGH CAPACITY MOBILE WORK BENCH			Aug. 2024
CATALOG NO.	48-22-8559	SERIAL NO.	M14A
		WIRING INSTRUCTION	

00 0

EXAMPLE:

Component Parts (Small #) Are Included When Ordering The Assembly (Large #).

●14-46-8559 Hardware Kit

11b	-----	Bolt M8 x 18L	(16)
11c	-----	Washer M8	(16)
4	-----	Bolt M4 x 12L	(14)
5b	-----	Bolt M6 x 16L	(4)
18a	-----	Bolt M4 x 16L	(12)
19	-----	Bolt M6 x 45L	(6)

NOTE: See page 2 for drawer slide removal and installation.




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	22-90-0105	Cord Grommet (Set of 1)	(1)	14	58-95-8559	Drawer Liner Kit (Set of 12) (Not Shown)	(1)
2	14-46-1645	Cord Storage Bracket Kit	(1)	15	12-20-0109	Service Nameplate (Not Shown)	(1)
3	-----	Cord Storage Bracket	(2)	17	12-25-1814	Electrical Label (Not Shown)	(1)
4	-----	Screw M4 x 12L	(4)	18	42-38-0269	Rear Bumper Kit (Set of 2)	(1)
5	14-46-1648	Side Handle Kit	(1)	18a	-----	Rear Bumper	(2)
5a	-----	Side Handle	(1)	18b	-----	Screw M4 x 16L	(4)
5b	-----	Bolt M6 x 16L	(4)	19	-----	Bolt M6 x 45L (Not Shown)	(6)
6	14-46-1342	Power Strip	(1)	20	31-01-8559	Steel Storage Logo Badge	(1)
8	14-46-1642	Drawer Slide Kit (Set of 2)	(1)	21	45-64-8553	52" Wood Top	(1)
8a	-----	Inner Drawer Slide	(2)				
8b	-----	Outer Drawer Slide	(2)				
8c	-----	5/32" Pop Rivet	(16)				
9	42-38-0272	Corner Bumper Kit (Set of 4)	(1)				
9a	42-38-0271	Corner Bumper/Extrusion Kit (Set of 2)	(1)				
9b	-----	Screw M4 x 16L	(8)				
9c	-----	Corner Bumper	(4)				
11	14-46-1245	Caster Kit (Set of 4)	(1)				
11a	-----	Swivel Caster w/ Brake	(2)				
11b	-----	Bolt M8 x 16L	(16)				
11c	-----	Washer M8	(16)				
11d	-----	Rigid Caster	(2)				
12	14-46-1643	Key/Lock Kit	(1)				
12a	-----	Key	(1)				
12b	-----	Lock	(1)				


FIG. NOTES

15,17 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

MILWAUKEE TOOL • www.milwaukeetool.com
13135 W. LISBON RD., BROOKFIELD, WI 53005


Drwg. 2

Cat. No. 48-22-8520 shown




Inner Slide

To remove drawer slide, remove rivets (15) from the inner slide (13) and outer slide (14) by 5/32" drill bit.




Outer Slide

To install drawer slide, place inner slide (13) into position and insert rivets (15) by using a rivet gun. Repeat steps for outer slide (14).



Inner Slide



Outer Slide