## WIRING INSTRUCTIONS

TITLE


## 12 VOLT "D"-HANDLE TOOLS

MILWAUKEE ELECTRIC TOOL CORP. 13135 WEST LISBON RD. BROOKFIELD, WIS

Date April '72

BULLETIN 58-01-0140

Wire No. 1 runs above field mounting boss.



USE LOCK WASHERS UNDER ALL SWITCH TERMINALS.

WHERE TERMINAL AND CONNECTOR COMBINATIONS ARE SPECIFIED, SEE ELECTRICAL PARTS CHART FOR PART NO. AND QUANTITY AND DRAWING FOR ACTUAL HOOK-UP

					٧	V I F	115	10	}	SF	<b>PE</b>	CIFICA	ATIC	NC	S				_		
Wire	Wire	Ga.	Lgth.					Connector				Wire	Wire	Ga.	Lgth.	Terminal					
Color	No.		in,	Tl	T2	T3	T4	Cı	C2	C3	C4	Color	No.	Ga,	in.	T1	T2	Т3	T4	C1 C2	C3C4
White	ı	Fld.	7-3/4	х					 		İ										
White	2	Fld.	4					x													
Black	3	Brsh.	5	х					i İ		! !										
Black	4	Brsh,	2-3/8					х													
Black	5	Cord	3-1/8		х				İ												
White	6	Cord	3-1/8		х																

NOTE:

ALL LEADS MUST BE HELD TO ± 1/8"
ALL FIELD LEADS TO BE MEASURED FROM
AND PERPENDICULAR TO LAMINATIONS.
ALL LEAD LENGTHS ARE BEFORE STRIPPING

THE ECAN CENTING ARE BEFORE STRIPPING								
Ele	ectrical Pa	rts						
TERMINAL DESCRIPTION								
Code	Part No.	Qnty.						
Τì	23-74-0330	2						
Т2	2 23-74-0210							
CONNECTOR DESCRIPTION								
Code	Part No.	Qnty.						
Сl	23-74-0200	2						
	WITCH DESCRIPTION							
Code		Qnty.						
\$1	23-66-0230	1						
		! !						