



SERVICE PARTS LIST

BULLETIN NO.
PN0004045

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS				REVISED BULLETIN	DATE
20A Power Manager					Nov. 2024
CATALOG NO.	3333-20A	SERIAL NO.	R27A	WIRING INSTRUCTION	




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	14-46-0924	Cable Management Clip Strap Assy.	(12)
2	10-22-1727	Warning Label (English)	(1)
3	12-20-0916	Service Nameplate	(1)
4	10-22-1728	Warning Label (Fr/Sp)	(1)

FIG.	NOTES
2,3,4	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.