



SERVICE PARTS LIST

BULLETIN NO.
PN0004809

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
M18™ TOP-OFF™ Charger & Power Supply				Aug. 2025
CATALOG NO.	2847-20	SERIAL NUMBER	WIRING INSTRUCTION	
		R47A		




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
4	42-92-7115	USB Cover	(1)
9	10-22-1995	Warning Label	(1)
11	10-15-9730	QR Code Label	(1)
12	12-20-9125	Service Nameplate	(1)
13	42-04-0820	Adapter 65W	(1)
14	42-44-0710	USB-C 100W Cable (3FT)	(1)

FIG.	NOTES
9,11,12	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.