



## TO INFORM YOU

PRODUCT  
SUPPORT  
BULLETIN #

134

---

**TO:**

Authorized Service Stations  
Branch Office/Service Centers  
Branch/Service Center Managers  
Regional Managers  
District Sales Managers

**DATE**

December, 1985

**FROM:**

Corbert A. Garb - National Service Manager

**TOOL(S)/PRODUCT(S) AFFECTED:**

6072 9" 5000 RPM Sander

---

**SUBJECT:**

02-04-1231 Ball Bearing \$4.85 List Price

02-04-1231 ball bearing is a NEW service part that uses a special corner radius on its inner ring ball race faces to improve the alignment of the bearing to the shoulder of the armature pinion shaft and spiral bevel pinion; which will reduce gear noise on the 6072 sander.

02-04-1231 ball bearing should be substituted for the 02-04-1230 ball bearing as needed when servicing 6072 sanders.

NOTE - 02-04-1230 ball bearing will remain a saleable service replacement part, as it is used in other MILWAUKEE products.

This bulletin is for informational purposes; please note on Service Parts List 54-38-0280.

---

MILWAUKEE ELECTRIC TOOL CORPORATION  
13135 W. LISBON RD., BROOKFIELD, WIS. 53005  
(414) 781-3600