



## TO INFORM YOU

PRODUCT  
SUPPORT  
BULLETIN #

143

**TO:** Authorized Service Stations  
Branch Office/Service Centers  
Branch/Service Center Managers  
Regional Managers  
District Sales Managers

**DATE** March, 1986

**FROM:** Corbert A. Garb - National Service Manager

**TOOL(S)/PRODUCT(S) AFFECTED:** 6145, 6145-2 4½" Angle Grinder  
Serial Number 627133000 and above.  
6146 5" Angle Grinder, Serial Number  
68413000 and above.

**SUBJECT:** 02-04-1005 Ball Bearing

To help prevent grease leakage through armature pinion ball bearing, the 02-04-1020 single contact seal type ball bearing should be substituted as needed, for the 02-04-1005 ball bearing originally installed in the affected angle grinders.

NOTE - 02-04-1005 ball bearing will remain a saleable service replacement part, as it is used in other MILWAUKEE products.

This bulletin is for informational purposes; please note on Service Parts List 54-38-0252, and -3502