



TO INFORM YOU

PRODUCT
SUPPORT
BULLETIN # 203

TO: Authorized Service Stations
Branch Office/Service Centers
Branch/Service Center Managers
Regional Managers
District Sales Managers

DATE June, 1990

FROM: Corbert A. Garb - National Service Manager

TOOL(S)/PRODUCT(S) AFFECTED: 5192 High Speed Die Grinder (serial # 669-33651 & above)

SUBJECT: Loosening of GEAR CASE mounting screws
(06-82-7299 8-16 x 7/8" Pan Head Plastite Screw)

If loosening of the gear case screws occurs on 5192 High Speed Die Grinder above serial # 669-33651, substitute four (4) 06-82-7326 8-16 x 1" Pan Head Plastite Screws for the four (4) 06-82-7299 *original equipment* 8-16 x 7/8" Pan Head Plastite Screws.

06-82-7326 8-16 x 1" Pan Head Plastite Screws increases the holding torque and clamping of the GEAR CASE to the 5192 MOTOR HOUSING.

Installing 06-82-7326 8-16 x 1" Pan Head Plastite Screw does not require any modification of MOTOR HOUSING gear case mounting holes.

This bulletin is for informational purposes; please note on Service Parts Lists 54-22-1023.

MILWAUKEE ELECTRIC TOOL CORPORATION
13135 W. LISBON RD., BROOKFIELD, WIS. 53005
(414) 781-3600