



## TO INFORM YOU

PRODUCT  
SUPPORT  
BULLETIN #

**204**

**TO:** Authorized Service Stations  
Branch Office/Service Centers  
Branch/Service Center Managers  
Regional Managers  
District Sales Managers

**DATE** June, 1990

**FROM:** Corbert A. Garb - National Service Manager

**TOOL(S)/PRODUCT(S) AFFECTED:** 8975 Heat Gun  
8977 Vari Temp Heat Gun

**SUBJECT:** 22-64-0830 16 2 SJ 8' 120V CORD SET  
44-76-0135 CORD PROTECTOR \ (Strain Relief)  
22-56-0470 TERMINAL BLOCK

Status of 22-64-4470 CORD SET for the 8975 & 8977 Heat Guns has recently been changed to Obsolete and Replaced by **22-64-0830** CORD SET.

A cord protector (strain relief) was included with the 22-64-4470 CORD SET and is NOT included with the 22-64-0830 CORD SET. If needed, order **44-76-0135** CORD PROTECTOR separately.

The terminal block connection between the SWITCH/PRINTED CIRCUIT BOARD & CORD SET is service replacement part number 22-56-0470 TERMINAL BLOCK.

This bulletin is for informational purposes; please not on Service Parts Lists  
54-05-0640 and -0650.

MILWAUKEE ELECTRIC TOOL CORPORATION  
13135 W. LISBON RD., BROOKFIELD, WIS. 53005  
(414) 781-3600