



TO INFORM YOU


**PRODUCT  
SUPPORT  
BULLETIN # 484**

TO: AUTHORIZED *portable electric tool* SERVICE STATIONS  
factory SERVICE / SALES SUPPORT BRANCH

DATE: May, 2008

TOOL(S) \ PRODUCT(S) AFFECTED: 8950 Series II and III Vacuum Cleaners, 8955 Series II and III & 4 Vacuum Cleaners

**SUBJECT: substituting Cartridge Filter 49-90-1830 for 49-80-0285 Cloth Filter Bag**




**49-90-1830  
Cartridge Filter**

**Cloth Filter Bag 49-90-0285** used with.....


- Series II and Series III **8950 Vacuum Cleaners**
- Series II, Series III, and Series 4\* **8955 Vacuum Cleaners is obsolete**

Anyone servicing or needing a Cloth Filter Bag 49-90-0285 can substitute the Cartridge Filter 49-90-1830. Foam Sleeve must be removed and discarded\*.

\* **Series 4** 8955 Vacuum Cleaners will have a wire cage (inside & outside) half along with four [4] wire cage retainers. These items will need to be removed and discarded when installing a cartridge filter. Cage retainer screws will be reused.



**Series II and III**



**Series 4**

This bulletin is for informational purposes. PLEASE NOTE ON SERVICE PARTS LIST: 54-05-0151, 54-05-0152, 54-05-0550, 54-05-0551 and 54-05-0552

---