TO: AUTHORIZED portable electric tool SERVICE STATIONS DATE: October, 2009


factory SERVICE CENTERS

**TOOL(S) \ PRODUCT(S) AFFECTED**: 2601-20 M18™ 1/2" Compact Driver Drill

SUBJECT: 22-56-1230 CONNECTOR BLOCK/PCB ASSY / 23-66-1195 Switch


23-66-1231 SWITCH & HANDLE HALVES SVC KIT

22-56-1230 CONNECTOR BLOCK/PCB ASSY and 23-66-1195 Switch [figs 12 & 29 on Service Parts List Bulletin 54-06-2610] for the 2601-20 M18™ 1/2" Compact Driver Drill are currently discontinued and being replaced by the 23-66-1231 SWITCH & HANDLE HALVES SVC KIT.



The PC Board is now internal to the switch. Wiring Instructions for the 23-66-1231 Switch are shown on page 2. Wires from the LED plug into the bottom of the switch body and are soldered to the terminal block as are the red & black switch leads — in a few instances 23-66-1231 SWITCH & HANDLE HALVES SVC KIT have been shipped minus the 14 gauge red & black switch wire and LED wires may not be soldered to the terminal box. Please use the wiring instruction found on page 2 to correct this situation.

## 23-66-1231 Switch Service Kit Wiring Instruction



WIRING SPECIFICATIONS				
Wire No.	Wire Color	Origin or Gauge	Length Inches	Terminals, Connectors and 1 or 2 End Wire Preparation
1	Black			Component of the Motor Assembly.
2	Red			Component of the Motor Assembly.
3	Gray			Component of the Switch Service Kit.
4	Green			Component of the Switch Service Kit.
5	Red			Component of the Switch Service Kit.
6	Black			Component of the Switch Service Kit.
7	White			Component of the Switch Service Kit.
8	Black	23-94-4240	2.75±.12	Component of the Switch Service Kit. Strip both ends to .20".
9	Red	23-94-0365	2.75±.12	Component of the Switch Service Kit. Strip both ends to .20".
BULK LEAD WIRE - BULLETIN NO. 58-01-0003				