

# TO INFORM YOU

## PRODUCT SUPPORT BULLETIN # 303

---

**TO:** AUTHORIZED *Portable Electric Tool* SERVICE STATIONS  
BRANCH OFFICE/SERVICE CENTERS, BRANCH MANAGERS  
REGIONAL MANAGERS, DISTRICT MANAGERS, SALES SUPPORT REPRESENTATIVES

**DATE:** APRIL, 1997

**FROM:** Corbert A. Garb - National Service Manager

**TOOL(S)\PRODUCT(S) AFFECTED:**

6507, 6508, 6509, 6511, 6512, 6535 SAWZALL  
6517, 6517-20, 6518 SAWZALL PLUS  
6527, 6528, 6537, 6537-22 SUPER SAWZALL

---

**SUBJECT: 22-18-0910 CARBON BRUSH ASSEMBLY**

**LIST PRICE \$ 1.35**

**22-18-0910 CARBON BRUSH ASSEMBLY** IS A NEW ONE PIECE CARBON BRUSH ASSEMBLY THAT IS REPLACING THE TWO PIECE, CARBON BRUSH (22-16-0275), BRUSH SPRING (23-52-0160) ARRANGEMENT CURRENTLY LISTED ON THE SERVICE PARTS LIST BULLETINS FOR SAWZALL, SAWZALL PLUS & SUPER SAWZALLS. 22-18-0910 CARBON BRUSH ASSEMBLY OFFERS A 25% INCREASE IN CARBON BRUSH LIFE, WITH LESS CHANCE FOR ARCING INSIDE THE BRUSH HOLDER AND AT THE COMMUATOR.

WHEN SERVICING 6507, 6508, 6509, 6511, 6512, 6535 SAWZALL, 6517, 6517-20, 6518 SAWZALL PLUS OR 6527, 6528, 6537, 6537-22 SUPER SAWZALL **IT IS RECOMMENDED THAT IF A CARBON BRUSH OR BRUSH SPRING REPLACEMENT IS NEEDED, THE 22-18-0910 CARBON BRUSH ASSEMBLY BE INSTALLED.** AS A FOOTNOTE, 22-18-0910 CARBON BRUSH ASSEMBLY SHOULD BE INSTALLED IN PAIRS, ONLY.

NOTE! ORIGINAL EQUIPMENT SHOWN ON SERVICE PART LIST FOR SAWZALLS, 22-16-0275 CARBON BRUSH AND 23-52-0160 BRUSH SPRING ARE CURRENTLY BEING USED IN OTHER PRODUCTS. THEREFORE, PLEASE NOTE THIS CHANGE TO THE 22-18-0910 CARBON BRUSH ASSEMBLY ON THE SERVICE PARTS LIST BULLETINS OF AFFECTED SAWZALLS: 54-40-0075, -0076, 0077, -0101, -0102, -0103, -0104, -0105, -0106, -0107, -0108, -0109, -0320, -0321, -0322, -0323, -0324, -0325, -0326, -0700, -0701, -0702, -0725, -0726, -0727, -0750, -0751, -4144, -4145, -4146, -4147, -4148, -4149, -4150, -4256, -4257, -4258, -4259, -4260, -4261, -4262, -5000, -5001, -5002, -5003, -5004, -5005, -5006, -5050, -5051, -5052, -5053, -5054, -5055, -5056, -5075, -5076, -5125, -5126, -5150, -5151, & -5152

This bulletin is for informational purposes.