

SERVICE PARTS LIST

BULLETIN NO. **54-04-1000**

SPECIFY CATALO	REVISED BULLETIN	DATE			
	- WIRING INSTR	July 2019			
CATALOG NO.	MXFC	STARTING SERIAL NO	K22A	WIRING INSTR	OCTION

EXAMPLE:

00 0

Component Parts (Small #) Are Included When Ordering The Assembly (Large #).

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	12-20-0202	Service Nameplate (Not Shown)	(1)
2	10-20-1773	Icon Label (Not Shown)	(1)

FIG. NOTES

1,2 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

