



SERVICE PARTS LIST

BULLETIN NO.
PN0004913

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
MILWAUKEE® RECHARGEABLE HEADLAMP AND MAGNETIC TASK LIGHT		54-06-2245	May 2025
CATALOG NO.	2012R	SERIAL NO.	M17B
		WIRING INSTRUCTION	

00 0

EXAMPLE:

Component Parts (Small #) Are Included
When Ordering The Assembly (Large #).

★ = Part number change from
previous service parts list.




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	45-56-2012	Strap	(1)
2	42-70-2103	Hard Hat Clips (Set of 4)	(1)
3	12-20-2012	Service Nameplate (Not Shown)	(1)
★ 4	31-15-0324	USB-C Cover	(1)
5	43-75-2012	Strap Holster Service Assembly	(1)
★ 6	48-59-1209	3ft USB-C and 2.1A Wall Charger(Accessory)	(1)
7	2012R	Rechargeable Headlamp & Magnetic Task Light	(1)

FIG. NOTES

- 3 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.