BULLETIN # 328

DATE: OCTOBER, 1998

TO: AUTHORIZED Portable Electric Tool SERVICE STATIONS

BRANCH OFFICE/SERVICE CENTERS, BRANCH MANAGERS

REGIONAL MANAGERS, DISTRICT MANAGERS, SALES SUPPORT REPRESENTATIVES

FROM: Corbert A. Garb - National Service Manager

TOOL(S) \ PRODUCT(S) AFFECTED

4202, 4203 Full-Wave Mag Stand, 4201, 4221, 4231 Half-Wave Mag Stand

SUBJECT: 23-35-0312 Full-Wave Magnetic Base Control Panel Kit – (4202, 4203 Mag Stand) List Price \$ 307.45

23-35-0321 Half-Wave Magnetic Base Control Panel Kit - (4201, 4221, 4231 Mag Stand)

SERVICE INSTRUCTION NOTE

23-35-0311 Control Panel can be replaced by one of two Control Panel service kits.

Ordering a 23-35-0311 Control Panel, the customer receives a 23-35-0312 Full-Wave Magnetic Base Control Panel Kit containing Control Panel, Lead Assembly, four (4) Dual Lock Velcro® Tabs, 54-30-0152 Control Panel Service Parts List and the following Service Instruction Note.

23-35-0312 FULL-WAVE MAGNETIC BASE CONTROL PANEL KIT, 23-35-0321 HALF-WAVE MAGNETIC BASE CONTROL PANEL KIT Service Instruction Note reads...

WARNING!

If a Full-Wave (23-35-0312) Panel Kit is installed into a Stand with a Half-Wave* Magnetic Base, the panel will be destroyed, when the magnet is energized. The entire panel will have to be replaced.

If a Half-Wave (23-35-0321) Panel Kit is installed into a Stand with a Full-Wave Magnetic base, the magnet will energize but, the motor will not function.

TO DETERMINE IF THE MAGNETIC BASE IS HALF-WAVE OR FULL-WAVE, DISCONNECT THE TWO (2) RED MAGNET LEADS FROM THE STAND'S CONTROL PANEL AND MEASURE THE RESISTANCE ACROSS THE LEADS. THE RESISTANCE OF A PROPER OPERATING FULL-WAVE MAGNETIC BASE WILL BE BETWEEN 97 AND 119 OHMS. A HALF-WAVE BASE WILL BE BETWEEN 37 AND 45 OHMS.

*When servicing a 4201, 4221 or 4231 Half-Wave Magnetic Base Stand the customer will need to use & have to re-order a 23-35-0321 Half-Wave Magnetic Base Control Panel Kit.

If you are able to **pre**-qualify the stand being repaired as a 4201, 4221 or 4231, you will save a circumstance of a 23-35-0312 Full-Wave Magnetic Base Control Panel Kit being returned for full credit.

This bulletin is for informational purposes; PLEASE NOTE ON SERVICE PARTS LIST BULLETIN: DOMESTIC, 54-46-2200, -2201, -2202, -2203, -2204, -2205, -2301, -2302, -2303, -2304, -2305, -2401, -2402, -2403, -2404, -2405, -2225, -2226, -2227, -2228, -2250