TO INFORM YOU

DATE: AUGUST, 1995

PRODUCT SUPPORT BULLETIN # 279

TO: AUTHORIZED Portable Electric Tool SERVICE STATIONS
BRANCH OFFICE/SERVICE CENTERS
BRANCH/SERVICE CENTER MANAGERS
REGIONAL MANAGERS
DISTRICT MANAGERS


FROM: Corbert A. Garb - National Service Manager

TOOL(S)\PRODUCT(S) AFFECTED:

1007-1, 1107-1 D-HANDLE DRILL; 5368-1 FALCON ROTARY HAMMER; 5398 1/2" HAMMER-DRILL; 6507, 6508, 6509, 6535 SAWZALL; 6517, 6518 SAWZALL PLUS; 6527, 6528 SUPER SAWZALL

SUBJECT: ELECTRICAL CONTINUNITY / RESISTANCE — 23-66-1490 VARIABLE SPEED SWITCH

WITH THE SWITCH CLOSED (TRIGGER IN 'FULL-ON' POSITION) THERE SHOULD BE CONTINUNITY BETWEEN T1 & T4, AND T2 & T5. FULL-ON RESISTANCE BETWEEN T3 AND T4 SHOULD BE 12K TO 30K OHMS (Ω).



This bulletin is for informational purposes. PLEASE NOTE ON SERVICE PARTS LIST 54-08-1205, -1206, -1207, -1208, -1209, -1215, -1216, -1217, -1218, -1219, 54-24-1308, -1340, -1341, 54-40-0075, -0076, -0077, -0106, -0107, -0108, -0109, -0322, -0323, -0324, -0325, -0700, -0725, -5000, -5001, -5002, -5003, -5004, -5005, -5050, -5051, -5052, -5053, -5054, & -5055